











PGE FAMILY, PGH FAMILY, PGA FAMILY

| SENSING RESISTORS | | |
|---|------------------------------|------------------------------------|
| Product | Features | Accessory For |
| PGE-600V Sensing Resistor  | Used on systems up to 1 kV. | PGR-5330 PGM-8325 |
| PGE-05KV Sensing Resistor  | Used on systems up to 5 kV. | PGR-5330 PGM-8325 |
| PGE-15KV Sensing Resistor  | Used on systems up to 15 kV. | PGR-5330 PGM-8325 |
| PGE-25KV Sensing Resistor  | Used on systems up to 25 kV. | PGR-5330 PGM-8325 |
| PGE-35KV Sensing Resistor  | Used on systems up to 35 kV. | PGR-5330 |

| TERMINATIONS AND ADAPTERS | | |
|--|---|---|
| Product | Features | Accessory For |
| PGH-5000 High Tension Couplers  | Allows 5-kV systems to be connected to relay. | PGR-3200 PGR-6100 PGR-8600 |
| PGA-0TA6 Termination Assembly  | 50 W ground-check termination with convenient mounting holes and screw terminals, temperature compensated. | PGM-8134 |
| PGA-0TA7 Small-Format Termination Assembly with Wire Leads  | 12 W ground-check termination, ideal for use in end caps and submersible pumps. Mounting holes and wire leads, temperature compensated. | PGM-8134 |
| PGA-0400 Port-Powered Serial Converter  | Converts an RS-485 signal to an RS-232 signal, used for set-point programming and updating flash memory. | PGR-6200 PGR-6300 PGR-7200 |
| PGA-0420 Serial Connector Adapter Kit  | Connects an RJ45 socket to a 9-pin serial connector, includes 1.5 m cable and plug-in adapter. | PGR-6200 PGR-7200 |